Stormwater Asset Management Plan Change Log

------Version 1 -----

| Edit Date | Section | Page | Edit |
|------------|----------------------------|------------------|--|
| 15/03/2021 | What We Have | Stormwater Pits | Council boundary layer changed from solid blue line to dashed line |
| | | Stormwater Pipes | Council boundary layer changed from solid blue line to dashed line |
| | What Condition are they in | Stormwater Pits | Council boundary layer changed from solid blue line to dashed line |
| | | Stormwater Pipes | Council boundary layer changed from solid blue line to dashed line |
| 16/03/2021 | What We Have | Overview | Data currency date included "Data as of: 20/21 Financial Year" |
| | What They're Worth | Overview | Data currency date included "Data as of: 20/21 Financial Year" |
| | What Condition are they in | Overview | Data currency date included "Data as of: 20/21 Financial Year" |
| 17/03/2021 | What we have | Stormwater Pits | Basemap change option added to map |
| | | | Popups configured and included in interactive map |
| | | Stormwater Pipes | Basemap change option added to map |
| | | | Popups configured and included in interactive map |
| | What Condition are they in | Stormwater Pits | Basemap change option added to map |
| | | Stormwater Pipes | Basemap change option added to map |
| 18/03/2021 | What Condition are they in | Stormwater Pits | Interactive legend added to map (based on condition filter) |
| | | Stormwater Pipes | Interactive legend added to map (based on condition filter) |

------Version 2 -----